

1、Low Pressure setting spindle
2、Differential setting spindle
3、Low Pressure Main arm
4、Low Pressure Main spring
5、Differenticl spring
6、Low Pressure Bellows
7、High Pressure setting spindle
8、High Pressure Main arm
9、High Pressure Main spring
10、Hich Pressure Bellows
11、Contact system
12、Terminal
13、Ground terminal
14、Cable entry
15、Brass nuts

					PRESSURE CONTROL DRAWING	060-124166R
						1 : 1
Design					2	2
		No.			РИДАН	
		DATE	2022/4/23			